

# Washable & Easy to Clean!

SlideMate™ REUSABLE is an amazing slide tube designed to help you transfer and reposition residents and patients safely, in a variety of healthcare settings. Its construction and design significantly minimizes the effort required by caregivers to move patients, preventing and reducing injuries.

The SlideMate™ is simple to use and cost effective. Using a SlideMate™ makes the repetitive and difficult tasks of repositioning and transferring easy. You will always want a SlideMate™ by your side!



## WHY SLIDEMATE?

- ✓ **Safety** Prevents injuries by significantly reducing the effort and forces required to perform lateral transfer and repositioning tasks.
- ✓ Quality Extremely durable material allows you to wash it while maintaining its slide effectiveness and wipe it down as needed.
- ✓ **User-friendly** It's simple and easy to retrieve when you need it.
  - **Color** Pleasant blue color makes it incredibly easy to work with and always find, while adding a calming patient visual experience.
- ✓ Versatile Useful for repositioning up in bed, transferring, turning, proning and and number of other assisted tasks.
- Sizing Available in two multiple sizes to meet your environmental 
  ✓ and resident / patient specific tasks.
- Cost It's a small price to pay to prevent injuries to your staff and ✓ patients. SlideMate™ makes a lot of cents!





#### **SIZES & SPECIFICATION**

Washable

- Individually sealed with insert
- Blue
- 100% silicone treated polyester taffeta.
- Sewn edges and join
- SWL 794lbs

#### 58" x 29" SLIDEMATE™ ORIGINAL

- 58" circumference
- Sold as Each (1)
- Individually bagged & sealed

CODE: **SMBH-5829R** QTY: **1 Each** 

#### 58" x 48" SLIDEMATE™ BARI

- 96" circumference
- Sold as Each (1)
- Individually bagged & sealed

CODE: **SMBH-5848R** QTY: **1 Each** 







### For more information or a free sample please email info@pelstarllc.com

# **CLEANING**

Wipe down with hospital approved disinfectant spray or wipes as needed. Or see Care Instructions below if a machine wash is necessary.

#### **CARE INSTRUCTIONS**

- Gentle wash between 149-176 °F in line with your thermal infection guidelines.
- Increase and decrease temperatures in stages as polyester can deteriorate with sharp increases in temperature.
- Use a mild soap.
- Avoid contact with chlorine, bleach, and alcohol.
- To dry, it is recommended to dry at cool temperature.
- Do not hot tumble dry.
- For longer life, hang SlideMate™ Reusuable tubes to dry and let dry naturally.



SlideMate is also available in 3 x Single Patient Use sizes

